	Туре	Hits	Search Text	DBs
1	BRS	5	6,246,558	USPAT; US-PGPUB
2	BRS	6	6,282,070	USPAT; US-PGPUB
3	BRS	0	6,0040,967	USPAT; US-PGPUB
4	BRS	25	6,040,967	USPAT; US-PGPUB
5	BRS	230	ground adj fault same filter	USPAT; US-PGPUB
6	BRS	18	ground adj fault same filter same transient	USPAT; US-PGPUB
7	BRS	12	ground adj fault same filter same surge	USPAT; US-PGPUB
8	BRS	1	ground adj fault same filter same MOV	USPAT; US-PGPUB
9	BRS	3	ground adj fault same filter same (MOV varistor)	USPAT; US-PGPUB
10	BRS	6	ground adj fault same filter same (LC capacitor adj inductor)	USPAT; US-PGPUB
11	BRS	12	ground same fault same filter same (LC capacitor adj inductor)	USPAT; US-PGPUB
12	BRS	6	5,892,667	USPAT; US-PGPUB
13	BRS	23	("4376243" "4466071" "4658322" "4709293" "4878144" "5185684" "5202662" "5206596" "5223795" "5224006" "5280404" "5432455" "5434509" "5459630" "5561505" "5590012" "5715125" "5805397" "5805398" "5815352" "5818237" "5835321" "5847913").PN.	USPAT
14	BRS	23	("4376243" "4466071" "4658322" "4709293" "4878144" "5185684" "5202662" "5206596" "5223795" "5224006" "5280404" "5432455" "5434509" "5459630" "5561505" "5590012" "5715125" "5805397" "5805398" "5815352" "5818237" "5835321" "5847913").PN.	USPAT
15	BRS	4	6088205.URPN.	USPAT

10/16/2002, EAST Version: 1.03.0002

	Time Stamp	Comments	Error Definition	Errors
1	2002/10/16 11:13			0
2	2002/10/14 14:51			0
3	2002/10/14 14:51			0
4	2002/10/14 14:58			0
5	2002/10/14 15:19			0
6	2002/10/14 14:59			0
7	2002/10/14 15:26			0
8	2002/10/14 15:26			0
9	2002/10/14 15:28			0
10	2002/10/14 15:31			0
11	2002/10/14 16:02			0
12	2002/10/14 15:36			0
13	2002/10/14 15:42			0
14	2002/10/14 15:46			0
15	2002/10/14 15:52			0

10/16/2002, EAST Version: 1.03.0002

	Туре	Hits	Search Text	DBs
16	BRS	2630	361/111	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	1054	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
18	BRS	38	(mov varistor) same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	0	sparc adj gap same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
20	BRS	0	sparc adj gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	0	sparc adj gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
22	BRS	0	sparc same gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	4	spark adj gap same filter same LC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	184	spark adj gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	351	Leviton adj Manufacturing	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
26	BRS	68	Leviton adj Manufacturing and ground same fault	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	4	Leviton adj Manufacturing and ground same fault same LC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	23	("4376243" "4466071" "4658322" "4709293" "4878144" "5185684" "5202662" "5206596" "5223795" "5224006" "5280404" "5432455" "5434509" "5459630" "5561505" "5590012" "5715125" "5805397" "5805398" "5815352" "5818237" "5835321" "5847913").PN.	USPAT
29	BRS	1054	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
16	2002/10/14 16:03			0
17	2002/10/15 09:38			0
18	2002/10/15 12:18			0
19	2002/10/15 12:19			0
20	2002/10/15 12:19			0
21	2002/10/15 12:20			0
22	2002/10/15 12:20			0
23	2002/10/15 12:21			0
24	2002/10/15 12:42			0
25	2002/10/15 12:42			0
26	2002/10/15 12:42			0
27	2002/10/15 12:53			0
28	2002/10/15 12:45			0
29	2002/10/15 12:55			0

	Туре	Hits	Search Text	DBs
30	BRS	935	361/93.6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
31	BRS	12	5,617,284	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
32	BRS	16	ground same fault same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	9	ground adj fault same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	64	ground adj fault same (mov varistor)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
35	BRS	5	ground adj fault same (mov varistor) same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	160	ground adj fault same (solenoid coil) same capacitor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	34	ground adj fault same (solenoid coil) same capacitor same filter .	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
38	BRS	573	361/85	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
39	BRS	64	(mov varistor) same bypass same capacitor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
30	2002/10/15 14:18			0
31	2002/10/15 15:24			0
32	2002/10/15 15:26			0
33	2002/10/15 15:29			0
34	2002/10/15 15:30			0
35	2002/10/15 15:59			0
36	2002/10/15 16:03			0
37	2002/10/15 16:04			0
38	2002/10/15 17:16			0
39	2002/10/16 11:15			0